

Parmit Type/ Number

## **Community Planning and Economic Development**

505 Fourth Ave. S., 320 Minneapolis, MN 55415

Office 612-673-3000 or 311, Fax 612-370-1416, TTY 612-263-6850

www.minneapolismn.gov

Data Issued

**Commercial Building Permit** 

App Phone #1: (952)698-7522  Idress: 10340 Viking Dr #105 App Phone #2:  Edwn Prairie, Mn 55344  PN: 2602924340125  Ite Address: 1807 ELLIOT AVE  Minneapolis, MN 55404  Pertificate of Occupancy: No  Permove stucco on back of building and replace siding. replace windows on east elevations.  807 and 1811 addresses.	· • · · · · · · · · · · · · · · · · · ·		<u> </u>			<u> </u>	<u> </u>				
Inspector Name Inspector Phone # Inspector email DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov eview the Record of Inspections with the Inspector to determine the required inspections  Decial Inspections  Piles, Piers Structural Steel Fireproofing Reinforcing Steel Welding Masonry Soil Retention System Wood  Masonry Soil Retention Spections above.	Commercial/BLDG929586		Commercial Multifamily		\$4,245.00	2/24/2022	3/3/2022				
Edwn Prairie, Mn 55344  N: 2602924340125  Re Address: 1807 ELLIOT AVE  Minneapolis, MN 55404  Pertificate of Occupancy: No  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding. replace windows on east elevations.  Brook of building and replace siding.  Brook of building and replace si	Applicant Name:	Atlas Restora	tion & Construction LLC		<b>App Phone #1:</b> (952)698-7522						
N: 2602924340125  te Address: 1807 ELLIOT AVE  Minneapolis, MN 55404  ertificate of Occupancy: No  th Description  emove stucco on back of building and replace siding. replace windows on east elevations.  807 and 1811 addresses.  spector  Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  eview the Record of Inspections with the Inspector to determine the required inspections  eview Inspections:  Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  my special inspection shown must be completed in addition to the required inspections above.	Address:	10340 Viking	Dr #105	Арр	Phone #2:						
Minneapolis, MN 55404  Pertificate of Occupancy: No  Sub Description  Semove stucco on back of building and replace siding. replace windows on east elevations.  BOT and 1811 addresses.  Sepector  Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  Eview the Record of Inspections with the Inspector to determine the required inspections  Percial Inspections:  Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  Inspections above.		Edwn Prairie	Mn 55344								
Minneapolis, MN 55404  Pertificate of Occupancy: No  Beh Description  Permove stucco on back of building and replace siding. replace windows on east elevations.  807 and 1811 addresses.  Sepector  Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  Eview the Record of Inspections with the Inspector to determine the required inspections  Percial Inspections:  Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  Provided the pr	APN:	260	2924340125								
ch Description  comove stucco on back of building and replace siding. replace windows on east elevations.  207 and 1811 addresses.  Spector  Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  Eview the Record of Inspections with the Inspector to determine the required inspections  Description	Site Address:		1807 ELLIOT AVE								
b Description  emove stucco on back of building and replace siding. replace windows on east elevations.  807 and 1811 addresses.  spector  Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  eview the Record of Inspections with the Inspector to determine the required inspections  pecial Inspections:  Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  ny special inspection shown must be completed in addition to the required inspections above.		Mir	nneapolis, MN 55404								
emove stucco on back of building and replace siding. replace windows on east elevations.  807 and 1811 addresses.  Spector  Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  eview the Record of Inspections with the Inspector to determine the required inspections  pecial Inspections:  Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  ny special inspection shown must be completed in addition to the required inspections above.	Certificate of Occ	upancy:	No								
Inspector Name Inspector Phone # Inspector email  DANIEL PEDERSON (612)685-8592 daniel.pederson@minneapolismn.gov  eview the Record of Inspections with the Inspector to determine the required inspections  pecial Inspections:  Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  ny special inspection shown must be completed in addition to the required inspections above.	Job Description										
Inspector Name  DANIEL PEDERSON  (612)685-8592  daniel.pederson@minneapolismn.gov eview the Record of Inspections with the Inspector to determine the required inspections  pecial Inspections:  Concrete  Piles, Piers  Structural Steel  Fireproofing  Reinforcing Steel  Welding  High Strength Bolting  Seismic  Wind  Masonry  Soil Retention System  Wood  my special inspection shown must be completed in addition to the required inspections above.			ling and replace siding. re	place windows	on east elevations.						
DANIEL PEDERSON  (612)685-8592  daniel.pederson@minneapolismn.gov  eview the Record of Inspections with the Inspector to determine the required inspections  pecial Inspections:  Concrete  Piles, Piers  Structural Steel  Fireproofing  Reinforcing Steel  Welding  High Strength Bolting  Seismic  Wind  Masonry  Soil Retention System  Wood  my special inspection shown must be completed in addition to the required inspections above.	Inspector										
eview the Record of Inspections with the Inspector to determine the required inspections  pecial Inspections:  Concrete  Piles, Piers  Structural Steel  Fireproofing  Reinforcing Steel  Welding  High Strength Bolting  Seismic  Wind  Masonry  Soil Retention System  Wood  my special inspection shown must be completed in addition to the required inspections above.	Ins	Ins	spector Phone #	ŧ	Inspector email						
Concrete Piles, Piers Structural Steel Fireproofing Reinforcing Steel Welding High Strength Bolting Seismic Wind Masonry Soil Retention System Wood ny special inspection shown must be completed in addition to the required inspections above.	DAN	J (	(612)685-8592	(	daniel.pederson@minneapolismn.gov						
Concrete Piles, Piers Structural Steel Fireproofing  Reinforcing Steel Welding High Strength Bolting Seismic  Wind Masonry Soil Retention System Wood  ny special inspection shown must be completed in addition to the required inspections above.	Review the Recor	d of Inspection	ns with the Inspector to de	etermine the red	quired inspections						
Reinforcing Steel  Welding  High Strength Bolting  Seismic  Wind  Masonry  Soil Retention System  Wood  ny special inspection shown must be completed in addition to the required inspections above.	Special Inspectio	ns:									
Wind Masonry Soil Retention System Wood ny special inspection shown must be completed in addition to the required inspections above.	Concrete		Piles, Piers	Structura	Steel	Fireproofing					
ny special inspection shown must be completed in addition to the required inspections above.	Reinforcing S	Steel	Welding	High Stre	ngth Bolting	Seismic					
	Wind		Masonry	Soil Reter	ntion System	Wood					
	 Any special inspe	ection shown n	nust be completed in addit	tion to the requ	ired inspections abo	ove.					
				to the requ							

- Other permits may be required including but not limited to electrical, mechanical, and plumbing
- For buildings with three or more dwelling units, windows installed under this permit shall meet the requirements of the current Minnesota State Building Code (MSBC), IBC Section 1026
- Emergency escape and rescue windows are normally required in sleeping rooms. The requirements for these windows are complex. If you did not have a plan review performed by the city and have not spoken with a qualified person regarding these requirements, it is recommended that you do so before purchasing or installing emergency escape and rescue windows. All replacement windows installed in a rental property or licensed facility (state or locally licensed) must meet the requirements of the most current Minnesota State Building Code (MSBC).
- Fall protection shall be provided according to MN Rule 1300.2300
- Safety glazing shall be required in hazardous locations designated in the MSBC
- Carbon monoxide detectors shall be installed according to MN State Statute 299F.50
- Smoke detectors shall be installed according to the MSBC

## **Permit Disclosure Information**

1 of 3 Permit #: BLDG929586 **RIGHTS UNDER PERMIT:** This permit is issued pursuant to the Minnesota State Building Code. This permit grants the right to perform the work described in the application submittal information and permit scope. This permit does not grant access rights to other structures or property and does not supersede the rights of other property owners who may be impacted by the work authorized herein.

**EXPIRATION:** This permit shall expire by limitation and is void if the work authorized is not commenced within 180 days after permit issuance, or if the work is abandoned for a period of 180 consecutive days.

**GRADING AND DRAINAGE:** No person may cause water to be diverted onto an adjacent property unless a legal easement exists for such purposes. Property owners must control drainage of water from their property in such a way that it does not cause a water drainage problem for any other property.

**REVOCATION:** This permit may be revoked upon violation of related state or local laws or ordinances.

REFUNDS: See Minneapolis Code of Ordinance, Section 91.15 for complete rules governing refunds.

Spanish - Atención. Si desea recibir asistencia gratuita para traducir esta información, llame (612) 673-2700
Somali- Ogow. Haddii aad dooneyso in lagaa kaalmeeyo tarjamadda macluumaadkani oo lacag la' aan wac (612) 673-3500.

Hmong Ceeb toom. Yog koj xav tau kev pab txhais cov xov no rau koj dawb, hu (612) 673-2800.

English- Attention. If you need this material in an alternate format, have questions, are deaf or hard-of-hearding, please call 612-673-3000.

TTY users can call 612-263-6850.

2 of 3 Permit #: BLDG929586



## Minneapolis — Construction Code Services Inspection Record

City of Lakes				IIISP	ection ite	coru				
Building Permit Number:	BLDG	929586		Address:	1807 ELLIOT AV	ľE				
Issue Date: 3/3/202	2	Applicant:	Α	Atlas Restorat	ion & Construc	tion LLC				
A/P Name: building	1807 ar	nd 1811 siding and	d wind	dows						
WARNING: No work shall rough-in work may be con above grade on the premise.	cealed p	orior to inspection	and	approval. Th	is card must be	posted in a consp	cuous pla	-		
REQUIRED INSPECTIONS		II	NSPE	CTION RECO	RD (DATE/INITI	ALS)		APPROVED		
Footing & foundation before placing concrete										
		Do not pour concrete until above has been approved.								
Under floor & slab after all in- slab and underfloor items are in										
place		Do not cover until above has been approved.								
Framing after all mechanical rough-ins are approved										
		Do not install insulation or covering until above has been approved.								
Insulation and vapor barrier prior to concealment										
		Do not install wall or ceiling finish until above has been approved.								
Lath and/or gypsum before taping or plastering  Final inspection after all work completed										
		Do not tape or seal wallboard or apply plaster until above has been approved.								
		To be made after final grading and other City Ordinano						es are completed.		
		PRELIMINARY		ROL	JGH-IN	FINAL		IN	ISPECTOR	
			Do r	not conceal b	efore rough-in i	is approved for eac	h permit	type		
Electrical (State of MN)										
Fire Suppression										
Gas, Steam, or Hot Water Piping & Heating										
Plumbing										
Warm Air – Ventilation Ai Conditioning	r									
Elevator										

No certificate of occupancy (when required) shall be issued until all permit work has been inspected and approved.

The contractor shall keep streets and alleys reasonably clean of dirt and debris from the project. Failure to comply will result in the Minneapolis Street Department cleaning the area and billing contractor for labor and equipment involved.

NOTE: Separate permits are required for all electric, plumbing, gas, oil, heating, ventilating, and refrigeration work.