



In order to replace the concrete entry to your home, the AC units need to be disconnected, moved off of the concrete, and reconnected after the concrete cures for 24-48 hours. **We need your assistance to ensure the removal and reinstallation is completed without issue.** This will disrupt your air conditioning while the AC is disconnected.

- **Units to be disconnected are 3862, 3864, 3808, 3766, 3684, 3674, 3672, 3517 & 3877.**
- **Brief access to your home/thermostat will be required to test for proper function during the disconnection.**
- **The scheduled date for the disconnect is Sunday, June 28th.**
- **The technician will be on-site starting at 9:00 am.**
- **Each disconnection will take 15-30 minutes to complete.**
- **Units can be stored in the lawn or garage but will need to be available for reconnection on Thursday the 2nd.**
- **The refrigerant will be pumped down and stored in the unit's condenser. There is no refrigerant lost during this process.**
- **"Weather permitting" Reconnection will take place on Thursday, July 2nd.**
- **The technician will be on-site at 8:00 am.**
- **If low, additional refrigerant can be added for an additional cost of \$75 per pound for R22 and \$50 for R410-A**


16526 W 78<sup>th</sup> Street, Suite 272

Eden Prairie, MN 55346 Main: [612-254-7373](tel:612-254-7373)

Email [Info@Atlasmn.com](mailto:Info@Atlasmn.com)



**Note: If access to the thermostat is not provided we cannot test for proper function. We will not be responsible for the performance of the system if access is not provided.**



**Please contact Justin Hamm with any questions or concerns.**

**Email: [Justin@Atlasmn.com](mailto:Justin@Atlasmn.com)**

**Cell: 612-644-5268**

**Project blog link**

**<https://atlasmn.com/2020/06/lodges-at-settlers-glen-concrete-and-asp-halt/>**

16526 W 78<sup>th</sup> Street, Suite 272

Eden Prairie, MN 55346 Main: **612-254-7373**

**Email [Info@Atlasmn.com](mailto:Info@Atlasmn.com)**