




Justin Hamm
Justin@Atlasmn.com
6122547373
Atlas Construction & Restoration

Copper Ridge Hail inspection
7/22/19, 7:01 AM
22

An inspection of the community was completed on Thursday, July 18th. Our inspection found enough damage caused by the weather event to file an insurance claim. The following report illustrates the damage caused by the storm. A more thorough inspection is required to document all of the damaged. This inspection should be completed after the claim has been filed and in conjunction with the insurance adjuster.

(1)



On July 17-18th 1"-2" hail was reported in the South Metro. The map shows the hail swath associated with this weather event.

(2)



All homes 700-756 Nicollet Blvd were inspected on July 18th.



Justin Hamm
Justin@Atlasmn.com
6122547373
Atlas Construction & Restoration

Copper Ridge Hail inspection
7/22/19, 7:01 AM
22

(3)



When entering in the community, it was obvious that hail had caused damaged. The trees had suffered significant leaf loss due to the hail.

(4)



Hail strikes to the trees and building materials left a mess and damage behind.

(5)



Multiple hail strike to the shingles.

(6)



Significant damaged caused to the shingle by a hale strike.

(7)



More shingle damage.

(8)



Enter a description

(9)



Hail strike.

(10)



Hail strike.

(11)



Hail strike.

(12)



Hail strike.

(13)



Vent cover missing due to high winds.

(14)



Furnace vent cover damage caused by hail strike.



(15)



Several hail strikes to the furnace exhaust cover.

(16)



Hail was large enough to damage the steel roof vents.



(17)



Damaged roof vent caused by hail strike.

(18)



Dented roof vent.

(19)



Damaged observed to the aluminum gutter caused by hail strikes.

(20)



Multiple dents found on downspout extension caused by hail strikes.

(21)



There were multiple hail strikes found on the vinyl siding.

(22)



The outside corner piece is off. Possible damage caused by the storm.

Inspection completed by Justin Hamm